


- *3 K30 needs sorting (or 2SK170, 2SK117, 2SK246)
- *5 Alternative to 2SC3423Y is TTC015B, etc.
- *6 Prevent oscillation and overshoot
- *7 Need Adjust
- *8 Solder on the back (Depends on board version)
- *10 Both resistors must match with accuracy.
- *4 Not required when using an external Low Boost switches
- *1 Depends on relay spec
- *12 941H-2C-12D 12V12.5mA 960Ω
- *2 LED brightness (Standby, Exec)



or Slide SW

TITLE		DRAWING_No.	
DC Pre Amp V1.4			
SHEET	DATE	DESIGN	
	2021/4/9	1975/11/17 org	