



DC servo is not recommended because it causes deterioration of sound quality. Also, there is no problem even if it does not exist. Attention to the withstand voltage of the regulator (7812 7912)

TITLE		DRAWING No.	
		Power Amplifier	
		V1.3	
SHEET	DATE	DESIGN	
/	2018/12/24		

